

RABINDRA BHARATI UNIVERSITY

RB/REG/299/ 2024

Dated: 08 01 2025

NOTICE

Sealed Quotations are invited from reputed & Experienced agencies for repairing of different type of split AC machine located at various department of Jorasanko campus, 6/4 D.N Tagore lane, Kolkata 700007, of Rabindra Bharati University as per ANNEXURE 1 & 2 within ten days from the date of the notice. Decision of the University regarding selection will be final & binding on all Agencies

Dr. Ashis Kumar Samanta Registrar (Acting)

ANNAXURE -1

Quotation are invited for Repairing of Split AC Machine_of difference type of <u>Blue Star / Voltas/Hitachi</u> make installed at Jorasanko Campus, of R.B.U., Kolkata. Details are given below

Sub.: Primarily Repairing of Split Air conditioners located <u>at various Departments of Jorasanko</u> Campus.

Room Air conditioners for repairing as detailed below.

Rate/Unit: Qty Amount inRs

1. 1 No. 2.0 Ton Blue Star AC at Bichitra Library :

- i) Replacement of 1 No. 2.0 Ton Compressor (New)
- ii) Vacumatizing the unit and charging fresh R-22 Gas.
- iii) Up-down transportation charges.

2. 1 No. 3.0 Ton Blue Star AC at Uday Sankar Hall:

- i) Replacement of 1 No. 3.0 Ton Compressor (New)
- ii) Vacumatizing the unit and charging fresh R-22 Gas.
- iii) Up-down transportation charges.
- iv) Cost of 1 No. Contract Relay.

3. A) 1No. 1.0 Ton Voltas AC at Chinese Gallery :

- i) Changing 1 No. Blower motor for Indoor unit.
- ii) Changing 1 No. Runner.

B) 1 No. 2.0 Ton Voltas AC at Conservation Lab. (inside of American Galary):

- i) Vacumatizing the unit and charging fresh R-22 Gas.
- iii) Repairing 1 No. PCB Circuit.
- iii) Changing 1 No. Blower motor for Indoor unit.

4. 2 Nos. 1.5 Ton Voltas AC at Chinese Galary:

- i) Replacement of 2 Nos. 1.5 Ton Compressor (New)
- ii) Vacumatizing the unit and charging fresh R-22 Gas.
- iii) Up-down transportation charges for 2 Nos. Split AC.

Page 1 of 2

Full 12025

Page 1 of 2

Rate/Unit: Qty Amount inRs

5. 1 No. 2.0 Ton Voltas AC at American Galary:

- i) Replacement of 1 No. 2.0 Ton Compressor (New)
- ii) Vacumatizing the unit and charging fresh R-22 Gas.
- iii) Up-down transportation charges.

6. A) 1No. 3.0 Ton Blue Star AC at Chinese Gallery :

Cost of 1 No. Contract Relay,

B) 1 No. 1.5 Ton Voltas AC at American Galary:

- i) Repairing of 1 No. Blower Motor for Outdoor unit.
- ii) Vacumatizing the unit and charging fresh R-22 Gas.

C) 1No. 2.0 Ton Hitachi AC at Cafetera:

i) Vacumatizing the unit and charging fresh R-22 Gas.

D) 1No. 2.0 Ton Hitachi AC at Souvenir Shop:

i) Vacumatizing the unit and charging fresh R-22 Gas.

B) 1No. 1.5 Ton Split AC at Thailand:

i) Wet Service charges for 1 No. 1.5 Ton Split AC..

Aug 101/2025
PSer Publi